Brumley South, Inc.


Part #188859-BSI Index #3

Made in USA. No Tariffs!
Enhanced Motor Driver Board 2025 Design!
For your….Tencor Surfscan 6000 Series!

Tencor Surfscan Life Extension!


THE PROBLEM:

OEM 20 year old part is showing signs of catastrophic failure of motor runaway with board destruction.



THE SOLUTION:

Enhanced 2025 Design resolves this catastrophic failure mode with increased reliability and reduces motor runaway.



We have designed New parts for your Surfscan to extend the life another Estimated 10 years!

DETAILS:

- Diagnostic LEDS and Test Points built in.
- Circuit Breakers Replaces Problem Fuses.
- 50% Cost reduction compared to the OEM!
- Direct Drop-In Replacement.
- Advanced Fail Safe Fire Protection!
- Tencor Systems - Guaranteed functionality!
- 12-Month Warranty - Buy with confidence knowing your investment is protected by Brumley South!
- Technical Support Available.

Prices:

Part Number 188859-BSI
Purchase outright : $15,000
Exchange : $9,500

SEMI/FOA 10% Discount available.

Now Available!

Parts Contracts for 100% Coverage!

SCAN FOR ADD'L UPGRADES >

Contact Information

Brumley South, Inc
422 N. Broad Street
Mooresville, NC 28115
Ph (704) 664-9251
Email: orders@brumleysouth.com

Date: 9 4 26