



Brumley South, Inc.



Tencor #238740 Replacement

GPIO PCB

For your Tencor Surfscan
6000 Series - New 2025 BSI
Advanced Design

DETAILS

- ✓ Advanced diagnostics feedback display
- ✓ Digital cassette sensor setup for pots
- ✓ Cost reduction compared to the OEM parts
- ✓ Direct drop-in replacement
- ✓ Tested on Tencor system - guaranteed functionality
- ✓ 12-Month Warranty
- ✓ Technical support available - troubleshooting assistance available
- ✓ Not sure if yours is faulty? We offer testing services and exchange circuit boards for reduced cost
- ✓ We have 100% replacement parts for your Surfscan tools
- ✓ Parts contracts for 100% coverage



Advances Diagnostic for Fast MTTR.

THE PROBLEM:

OEM has no more stock on new parts for the Tencor Surfscan tools.

THE SOLUTION:

Newly designed Tencor Surfscan GPIO PCB, engineered exclusively by Brumley South to replace old, failing, obsolete OEM Parts.

NEW Replacement parts for your Surfscan tools to extend the life another, estimated, 10 years!

Part Number 238740-BSI

Purchase outright : \$18,000

Exchange : \$9,500

SEMI/FOA 10% discount available



Made in USA. No Tariffs!



(704) 664-9251 ext. 204



orders@brumleysouth.com



Brumley South, Inc 422 N. Broad
Street Mooresville, NC 28115



brumleysouth.com