




Brumley South, Inc.

MDD Board - Enhanced Motor Driver Board 2025 Design!

Tencor Surfscan 6000 Series!


Part # 188859-BSI Index #3

Tencor Surfscan Life Extension!



THE PROBLEM:

The OEM 20-year-old part is showing signs of catastrophic failure, including motor runaway and board destruction.



THE SOLUTION:

The enhanced 2025 design resolves this catastrophic failure mode, increases reliability, and reduces motor runaway.

Now Available! Parts Contracts for 100% Coverage!

Prices:

Purchase outright : \$15,000

Exchange: \$9,500

SEMI/FOA 10% Discount available.



Made in USA. No Tariffs!

DETAILS

- ✓ Diagnostic LEDS and test points built in
- ✓ Circuit breakers replace problem fuses
- ✓ 50% Cost reduction compared to the OEM
- ✓ Direct drop-in replacement
- ✓ Advanced fail-safe fire protection
- ✓ Tencor Systems - Guaranteed functionality
- ✓ 12-month warranty - Buy with confidence
- reboots
- ✓ Technical support available



(704) 664-9251 ext. 204



orders@brumleysouth.com



Brumley South, Inc 422 N. Broad Street Mooresville, NC 28115



brumleysouth.com

Date: 2/2026